



EXHAUST FAN REPAIR.

Location: **GILLESPIE RESEARCH.**

Disruption/Outage: **REDUCED EXHAUST FLOW.**

Date: **SATURDAY 04/26/2025.**

Duration: **5AM THRU 5PM, 12HRS.**

Details: **REPLACE THE MOTOR AND BEARINGS
ON EXHAUST FAN 4.**

We appreciate your cooperation and apologize for any inconvenience this may cause.
If you have any questions or concerns, please contact Facilities Tony Garrit, at 949-824-5140 or tgarrit@uci.edu

Cc: Building Facility Manager (please route to appropriate MSO/affected faculty and/or staff)

DATE POSTED:
PLEASE POST UNTIL: